

We took the services to detect the source of seepage in my home. We could see the walls and the sides of doors getting damaged but couldn't locate the actual source of seepage.

The entire inspection took close to 2 hours. A team of 3 people came with the thermal scanning machine. They inspected each and every wall, bathrooms, balconies. To my surprise not only was the bathroom our source of seepage but also one of the balcony. A detailed report was shared with us which made it very simple to know the real reason of our problem. And now when we know the root cause we will be able to fix it once and for all. The report shared with us is extremely detailed and easy to understand for a layman. I must also appreciate the people who came to inspect the house, they were extremely professional and done their work very diligently.

I will definitely recommend to anyone dealing with seepage issue. Once the root cause is fixed the problems no longer exists.

Best regards
Nirmal Kishore